REMARKS

Figure 2 has been amended to more clearly identify reference sign 114 and to delete reference sign 111. Figure 3 has been amended to remove reference sign 123. No new matter has been added.

The Examiner has objected to the drawings under 37 CFR 1.84(p)(5) because the Examiner was unable to find a description of reference signs 111, 115, and 123 in the specification. Reference sign 115 is described as a "base plate" on page 6, line 2, of the specification. Reference signs 111 and 123 have been removed from the drawings. Accordingly, this rejection should be withdrawn.

The Examiner has also objected to the drawings under 37 CFR 1.84(p)(5) because the Examiner was unable to find reference sign 114 in the drawings. Reference sign 114, which identifies an "end plate", can be found in Figure 2 as filed. Figure 2, has been amended to make reference sign 114 more clear. Accordingly, this rejection should be withdrawn.

Finally, the Examiner has objected to the drawings under 37 CFR 1.83(a), because the Examiner can not find support in the drawings for "the support member," "the two mold cavity members and their holding sections," and "the mold cavity housing." This rejection is respectfully traversed. The drawings depict specific embodiments of the inventions. The specification and claims are directed to more general embodiments of the invention.

Accordingly, the claims and specification often use more generic names than the names used in the Figures. One of ordinary skill in the art would easily identify that the chase base 122, found in Figure 3, as the support member. The left and right cavity bars 119 and 120 are the two mold cavity members. The "chase block 118" is the mold cavity housing. Finally, the holding sections are described in the Abstract as a ". . . a first holding section for holding a first mold half (119) and a second holding section for holding a second mold half (120). The first and second holding section has a common support surface (135), the support surface (135) including a first movable member (104a) in the first holding section and a second moveable member (104b) in

the second holding section." This description of the holding sections provides a detailed description of the holding section with reference to the figures. In view of this description, one of ordinary skill in the art would not need the holding sections particularly pointed out to identify the holding sections. Accordingly, this rejection should be withdrawn.

The Examiner has allowed claims 1-9. In view of the amendments made to the drawings and the foregoing remarks, a notice of allowance is solicited.

In the event that the transmittal letter is separated from this document and the Patent and Trademark Office determines that an extension and/or other relief is required, applicants petition for any required relief including extensions of time and authorizes the Commissioner to charge the cost of such petitions and/or other fees due in connection with the filing of this document to **Deposit Account No. 03-1952** referencing docket no. <u>532432000200</u>.

Respectfully submitted,

Dated:

August 12, 2003

By:

Jonathan Bockman
Registration No. 45,640
Morrison & Foerster LLP
1650 Tysons Blvd, Suite 300

McLean, Virginia

Telephone: (703) 760-7748 Facsimile: (703) 760-7777

va-41273